

Belrose

Licence Number: 5180

Licence Holder: EDL LFG (NSW) PTY LTD

Licencee Address: Belrose LFG Power Station, Crozier Rd, Belrose NSW 2085

Testing Year: 2018

Testing Required: Discharge and Monitoring Point: Discharge and monitoring point 7 - Flare Unit 01

Testing Frequency: Each Engine Exhaust (Points 1-5), Supply Line (Point 6) and Flares (Points 7-8) are to be sampled once every 5 years.

Location of Monitoring Point	Sampled	Obtained	Published	Pollutant	Units of Measure	Licence limit	No. Samples Required by Licence	No. Samples collected and Analysed	Value
Monitoring Point 7, Flare Unit 01	12/10/2018	7/11/2018	21/11/2018	Volumetric flowrate	Cubic metres per second		1	1	12
				Temperature	Degrees Celsius	>760	1	1	768
				Residence time	Seconds	>0.6	1	1	1.8
				Moisture content	%		0	1	6
				Velocity	m/s		0	1	4.6

Note: The Engines for Monitoring Points 1, 3, 4 and 5 are not installed on site - no monitoring is applicable

Change Log

Date Change

24/07/2020 Inserted Testing Frequency into data sheet

24/07/2020 Included note regarding apparent missing data

24/07/2020 Replaced 'Min', 'Mean' and 'Max' column titles with 'Value'